

The improvement was made by the change illustrated on this page. The quick-connect fitting was removed from each hose indicated by a colored arrow and the hose was moved to a burred connector mounted in the capped hole indicated by the arrow of the same color. The bottom two pictures show the low noise configuration.

