



Top 2 photos are of nozzles in the 2K IMC tube. Bottom photo is of a nozzle in HAM3. There is much less particulate in the nozzle suggesting that vacuum cycling is not redistributing the particulate rapidly.

